

U.S. Department of Transportation

400 Seventh Street, SW Washington, DC 20590

National Highway Traffic Safety Administration

AUG 1 1 2006

MR. JOSEPH THOMPSON GENERAL MANAGER ROUSH PERFORMANCE PRODUCTS, INC. 28156 PLYMOUTH ROAD, SUITE Z LIVONIA, MI 48150 NVS-215kjs 06E-071

Subject: FRONT STRUT BRACKET SEPARATION

Dear MR. THOMPSON:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORD/MUSTANG GT/2005-2006 ROUSH/401296/9999 ROUSH/401297/9999

NHTSA Campaign Number: 06E-071 Mfg's Report Date: August 7, 2006

Components:

SUSPENSION: FRONT

Potential Number of Units Affected: 146

Summary:

CERTAIN AFTERMARKET ROUSH BRANDED FRONT STRUTS AS A STAND ALONE COMPONENT, PART NO. 401297, AND ROUSH BRANDED FRONT STRUTS AS A SUSPENSION KIT, PART NO. 401296, SOLD FOR USE ON 2005 AND 2006 FORD MUSTANG GT VEHICLES. THE FRONT ANTI ROLL BAR ATTACHMENT BRACKET ON THE FRONT STRUT CAN SEPARATE FROM THE STRUT HOUSING DUE TO INCONSISTENT WELDING. THIS COULD RESULT IN A CLUNKING NOISE AND/OR POOR HANDLING IN EXTREME OR EMERGENCY MANEUVERS.

Consequence:

IF THE BROKEN BRACKET CONTACTS THE TIRE, SIDEWALL DAMAGE CAN OCCUR, POSSIBLY RESULTING IN A VEHICLE CRASH.

Remedy:

ROUSH WILL NOTIFY OWNERS AND OFFER TO PROVIDE NEW STRUTS FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING AUGUST 2006. OWNERS MAY CONTACT ROUSH AT 734-466-6255.

Notes:

THIS RECALL ONLY PERTAINS TO AFTERMARKET ROUSH BRANDED FRONT STRUTS AND SUSPENSION KITS AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON FORD MUSTANG GT VEHICLES MANUFACTURED BY FORD MOTOR COMPANY. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Roush must file a sample of the envelope which you intend to use to mail the recall notice to owners. The words "SAFETY", "RECALL", "NOTICE" in any order must be printed on the envelope in larger font than the customers name and address.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, the recall is expected to begin during August 2006. Therefore, the first quarterly report will be due in this office on or before 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227 or by email at KSCHULER@NHTSA.DOT.GOV. We look forward to working with you for successful completion of this recall campaign.

Sincerely

George H. Person

Chief, Recall Management Division Office of Defects Investigation Enforcement

cc: Erica Jones and Ken Weinstein

Mayer, Brown, Rowe & Maw LLP